


⊗ CABLE AT THE BOTTOM *OR*
ON TOP OF THE STAIRCASE

QUARTER-TURN STAIRCASE - 2 HANDRAILS
(turning steps middle)



CORNER:
CONNECT THE CABLE
IN THE PLASTER