

## QUARTER-TURN STAIRCASE (turning steps below)

- ⊗ CABLE AT THE BOTTOM OR  
ON TOP OF THE STAIRCASE

LENGTH HANDRAIL EVERY 5CM BETWEEN 100 - 580 CM

min.10 CM

90 CM

$\frac{\text{WIDTH}}{2}$

⊗ CABLE  
24V=

90 CM

WIDTH

