

QUARTER-TURN STAIRCASE - 2 HANDRAILS (turning steps middle)

- ⊗ CABLE AT THE BOTTOM OR
ON TOP OF THE STAIRCASE



QUARTER-TURN STAIRCASE - 2 HANDRAILS
(turning steps middle)

⊗ CABLE AT THE BOTTOM OR
ON TOP OF THE STAIRCASE

LENGTH HANDRAIL EVERY 5CM BETWEEN 100 - 580 CM

min.10 CM

90 CM

$\frac{\text{WIDTH}}{2}$

90 CM

CORNER:
CONNECT THE CABLE
IN THE PLASTER

